

# SEPTIC INSPECTION REPORT

# Collins Sanitary LLC

W9235 County Road B, Clinton Wisconsin 53525

Phone: (608)676-4432 or (800)742-1893

Fax: (262)736-2248

Date of Inspection: 4.22.20  
 Name: Immobly Assets  
 Address: 972 Phythover Rd.  
 City/State: Beloit, WI.  
 Phone: 815-623-5555  
 Number of Bedrooms: 3

Realtor/Agent: \_\_\_\_\_  
 Phone: \_\_\_\_\_  
 Fax: \_\_\_\_\_  
 Email: debo@gogambino.com

### TYPE OF SEPTIC SYSTEM

Conventional:   
 Holding Tank:   
 Mound System:

### TYPE OF DRAINFIELD

Seepage Trench:   
 Drywell:   
 Mound:

### Drywell Measurements:

|             |      |
|-------------|------|
| Total Depth | 156" |
| Water Level | 86"  |
| Pipe Level  | 93"  |

### MATERIAL

Precast:   
 Plastic:   
 Fiberglass:   
 Steel:   
 Block:

### INSPECTION SUMMARY

A = Adequate      D = Disintegrating      I = Inadequate      N/A = Not Applicable

### INSPECTION OF TANK

|  |         |
|--|---------|
| Date pumped:                           |         |
| Approximate age:                       | 70+ yrs |
| Did the drainfield backflow into tank? | NO      |
| Condition of tank:                     | A       |
| Condition of baffles:                  | A       |
| Condition of manhole & risers:         | A       |
| Condition of lift station:             | N/A     |
| Condition of electrical components:    | N/A     |
| Was there a lock on the cover?         | NO      |
| Was there a warning label?             | NO      |
| Were there signs of leakage/overflow?  | NO      |

### INSPECTION OF SOIL ABSORPTION SYSTEM

|                                       |                                     |
|---------------------------------------|-------------------------------------|
| Approximate age:                      | 70+ yrs                             |
| Was the drainfield located?           | Yes                                 |
| Was there an odor?                    | NO                                  |
| Did the ground show signs of ponding? | NO                                  |
| Was liquid present in the vent pipe?  | NO                                  |
| Drywell                               | <input checked="" type="checkbox"/> |
| Field Tile                            | <input type="checkbox"/>            |
| Observation Port                      | <input type="checkbox"/>            |

The onsite wastewater treatment system at this site appeared to be functioning properly at the time of this evaluation

The onsite wastewater treatment system at this site did not appear to be functioning properly at the time of this evaluation

\*\*Please see additional comments for the reason\*\*

**Additional comments on septic system:**

Collins Sanitary LLC does not guarantee the life expectancy of the septic system

Wisconsin License # 978  
 Illinois License # 054-007018

  
 Thomas M. Collins  
 Collins Sanitary LLC