



CORRESPOND TO:
Consultant Engineering Services PLLC
PO Box 1125
Troy, NY 12181
518-796-6349

October 17, 2024

0 Lolick Lane
Glenville, New York 12302

SUBJECT: Perc & Deep Hole Report
SITE LOCATION: 0 Lolick Lane Glenville, New York 12302

This letter transmits the results of perc and deep hole tests that were performed at the address stated above. The test was performed at your request in order to determine the septic design conditions. The tests were performed by Robert Mann, PE of Consultant Engineering Services, PLLC on October 15, 2024, Deep Hole and perc test.

TEST DATA

Perc test holes 1 & 2 18" below grade.

PERC TEST DATA:

PT1- 25:43 MIN/INCH STABILIZED

PT2- 55:11 MIN/INCH STABILIZED

Design to 6-7 MIN/INCH

TEST PIT HOLE

0" TO 4" Top Soil/Sand/Loam

4" TO 19" Light clay/sand

19" TO 59" dark clay

Ground water, molting at 23"

Bedrock at 59"



Figure 1 – Deep Test Pit Hole



Figure 2 – Wall of Deep Test Pit Hole



Figure 3 – Perc Test Holes

These findings and results are based on information available at the time of the test and I reserve the right to change my opinion if new information becomes available. This report is not meant to be or imply a warranty against, past, present, or future conditions.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert V. Mann". The signature is fluid and cursive, with a long horizontal flourish at the end.

Robert V. Mann, PE Lic. # 096034