

It looks like you have two Reverse Osmosis systems. The first is a standard 4 stage reverse osmosis system with a 50 GPD membrane and a 4 gallon storage tank. The second 4 stage reverse osmosis system with a 150 GPD membrane and a 9 gallon storage tank. Just as a reminder, it looks like you are due for filter changes on both ROs. If that is something the new owners would like to do through us, please let me know! For information about each of the filters and suggested filter change schedule, please see the packet below.

You also have a whole home water softener with KDF cubes. KDF is used to remove iron/sulfur. This is a product that we have stopped recommending because it requires repacking the softener every 2-5 years instead of every 7-10 years. Once the KDF is exhausted, the softener still works to reduce hardness but you will notice the sulfur smell/iron rings again. If iron/sulfur is a concern, we have better long term solutions that require far less maintenance.

I hope this is helpful! I have attached some packets on these systems. If you or the new homeowners have questions, please feel free to reach out to us!

**Norah Wagner**

Office Administrator

Phone: (817) 295-8514

Email: [admin3@iwantpurewater.com](mailto:admin3@iwantpurewater.com)

Address: 234 SW Wilshire Blvd. Burleson, TX