				. /
WJR-26-77			Ver 1	a da a
COLORADO DIVISION O THIS FORM MUST BE SUBMITTED WITHIN 60 DAYS OF COMPLETION OF THE WORK DESCRIBED HERE- ON. TYPE OR PRINT IN BLACK INK. WELL COMPLETION AND PUN INK. WELL OWNER <u>Richard B. Hayes</u> 2265 Monico Parkway			Received eet - Room 818 brado 80203 MP INSTALLATION REPORT	
			<u>NW</u> % of the <u>SW</u> % of Sec. <u>15</u>	
ADDRESS Denver, Co. 80207		T. <u>23 S., R. 71 W., Otn</u>	_ P.M.	
DATE COMPLET	ED 10/17	, 19 <u>81</u>	HOLE DIAMETER 8	
	WELL LOG	Water	<u>6 in from 19 to 243 ft.</u>	
From To 0 61 80 82 82 105 105 112 112 116 116 198 198 234 234 243	Volcanic mud flow red ryolite fractute red ryolite fracture ryolite yellow clay w/ryolite fracture ryolite fracture ryolite brown ryolite	XX	in. fromtoft. DRILLING METHODAir CASING RECORD: Plain Casing Size <u>6 5/8</u> & kind <u>steel</u> from <u>+1</u> to <u>19</u> Size <u>4"</u> & kind <u>plastic</u> from <u>9</u> to <u>143</u> Size <u>8</u> kind <u>plastic</u> from <u>143</u> to <u>24</u> Size <u>8</u> kind <u>plastic</u> from <u>143</u> to <u>24</u> Size <u>8</u> kind <u>plastic</u> from <u>143</u> to <u>24</u> Size <u>8</u> kind <u>from</u> to <u>5</u> Size <u>8</u> kind <u>10/17</u> , 10 Static Water Level Prior to Test <u>140</u> Type of Test Pump <u>air</u>	9 81 ft.
_ = *.			Length of Test4 hours	
Use a	TOTAL DEPTH <u>243</u> dditional pages necessary to complete log.		Sustained Yield (Metered) <u>2.25 G.P.M.</u> Final Pumping Water Level <u>223</u>	